

28/11/2017

These are the following materials required for spares of Type-HWX Vacuum circuit breaker Panels in Mines sub-station:

S. No	Material code	Material Description	Model No.	Quantity	Make
1	400007013 061	BUFFER for opening spring	MVIJ00098-01	09 No's	Schneider
2	400007013 062	BUFFER for closing spring	MVIJ00056-01	09 No's	Schneider
3	400007013 064	Spring charge motor, 230v,A.c supply	MVIJ00157-03	01 No.	Schneider
4	400007013 065	Shunt trip coil, 110V DC supply	ECO39SN134100FN	6 No's	Schneider
5	400007013 066	Release coil, 110V DC supply	ECO39SN134900FN	3 No's	Schneider


28/11/18

P.S.Rao

Addl.Suptd.(Elect)

UCIL, TMPL Mines