

SPECIFICATION FOR TOXIMETER

Make: RAE, USA

Model: QRAE-Plus

Specification:

| Parameter | CO | SO ₂ | NO ₂ | O ₂ |
|------------|-----------------|-----------------|-----------------|-----------------|
| Range | 0-500 PPM | 0-20 PPM | 0-30 PPM | 0-25 % |
| Resolution | 1 PPM | 0.1 PPM | 0.1 PPM | 0.1% |
| Sensor | Electrochemical | Electrochemical | Electrochemical | Electrochemical |

Features:

- Powerful Internal Pump
- Ideal for leak detection and site surveys
- Visual Alarm with Flashing LED
- Large keys usable with gloved hand
- Rechargeable Battery
- Display Graphic: 4 Lines, with LED automatic back light in dim light or alarm condition.
- CD ROM with computer interface cable.

With Standard Accessories