

Annexure: Spare motors for drying plant

SI No	Material Code	Description	Qty
1	300 008 026 100	3 phase squirrel cage induction motor, KW: 0.75, 1410 rpm, 4 pole, foot mounting, Frame: ND80, IE2 eff, Make: Crompton/ABB/Siemens	1
2	300 008 026 101	3 phase squirrel cage induction motor, KW: 0.75, 2820 rpm, 2 pole, foot mounting, Frame: ND80, IE2 eff, Make: Crompton/ABB/Siemens	1
3	300 008 026 102	3 phase squirrel cage induction motor, KW:1.1, 935 rpm, 6 pole, foot mounting, Frame: ND100L, IE2 eff, Make: Crompton/ABB/Siemens	1
4	300 008 026 103	3 phase squirrel cage induction motor, KW:11, 2920 rpm, 2 pole, foot mounting, Frame: ND160M, IE2 eff, Make: Crompton/ABB/Siemens	1
5	300 008 026 104	3 phase squirrel cage induction motor, KW:11, 1440 rpm, 4 pole, flange mounting, Frame: ND160M, IE2 eff, Make: Crompton/ABB/Siemens	1
6	300 008 026 099	3 phase squirrel cage induction motor, KW:1.5, 1410 rpm, 4 pole, flange mounting, Frame: ND90L, IE2 eff, Make: Crompton/ABB/Siemens	1
7	300 008 026 105	3 phase squirrel cage induction motor, KW:2.2, 1410 rpm, 4 pole, flange mounting, Frame: ND100L, IE2 eff, Make: Crompton/ABB/Siemens	1
8	300 008 026 098	3 phase squirrel cage induction motor, KW:3.7, 2820 rpm, 2 pole, foot mounting, Frame: ND100L, IE2 eff, Make: Crompton/ABB/Siemens	1

Handwritten signature
10/4/19