

URANIUM CORPORATION OF INDIA LIMITED
P.O.- JADUGUDA MINES, EAST SINGHBHUM, JHARKHAND

UCIL/Mill/131/45/2023

January 19, 2023


NOTICE INVITING TENDER

Sealed quotations are invited from individual /firm for outsourcing of 17 unskilled manpower for Jadugoda Mill for a period of 40 days including Sunday & holiday.

Terms & Conditions:

1. The quotation to be addresses to the Superintendent (Mill), UCIL(Mill) Jadugoda, P.O.-Jadugoda Mines, East Singhbhum, Jharkhand-832102 as per attached format with acceptance of terms & conditions mentioned in the format.
2. UCIL has the right to accept or reject any or all the application without any assigning a reason thereof.
3. The time and date of submission of quotation is 3.00 pm on 27.01.2023 (i.e. 27thJan.2023).The quotation shall be opened on the same day at 3.30 P.M.

Yours Truly
For Uranium Corporation of India Limited


19/1/23
Chief Supdt.(Mill)/In-charge



Copy forwarded to:

1. Supdt.(CP)- Kindly publish & upload in UCIL web page.
2. Notice Board
3. File No. : 131

SCHEDULE OF ITEM & RATERef: UCIL/Mill/131/45/2023 Dated: 19/01/2023

Sl. No.	Description	No. of manpower required (A)	Working days (B)	Rate per manpower/day/(Rs.) Incl. of GST and other charges (C)		Amount (Rs.) Incl. of GST and other charges (D) = AxBxC	
				(in figures)	(in words)	(in figures)	(in words)
1.	Outsourcing of Unskilled Manpower	17	40				

OTHER TERMS AND CONDITIONS:**1. Security Money Deposit:**

Security money deposit equivalent to 03 (three) % of the ordered value is required to be deposited in accounts Department-UCIL in the form of demand draft before the start of the work 100% security deposit will be refunded on written request in duplicate to the engineer -in-charge after completion of work.


2. Completion Time:

40 (forty) days (including Sunday & holiday) from the date of commencement of work at site.



Ref: UCIL/Mill/131/45/2023 Dated: 19/01/2023

3. Payment Terms:
02(Two) R A & 1 (One) Final Bill will be paid against this work after submission of quadruplicate bill. Final bill should be submitted within 07(Seven) days from the date of completion.
4. Working period:
A, B, C & General Shift (including Sunday & holiday) as per direction of Engineer –in-charge.
5. Supply of Manpower:
17 unskilled manpower to be supplied every working day (including Sunday & holiday) during contract period.
6. Rate:
The rate shall be quoted by the contractor must include all taxes (GST) & Duties, PF, PPE, Insurance, etc. No extra payment will be entertained after rate quoted by the contractor.
7. Minimum wages, EPF, Bonus, Insurance, Safety appliances and tools & tackles, contractor's profit should be included in quoted rate. No extra payment will be made thereafter.
8. Party has to submit hard copies of PAN Card, GSTIN, & EPF registration number.
9. If any discrepancy found in figure & words of rate or amount of the price bid then rate or amount in words will be treated as final.
10. Accepting the all terms and conditions.


Raja Sinha
Supdt. (Mill)

SCOPE OF WORK

1. Scope of Work:

The scope of work per shift under this tender is as follows:

- a) To work in running shifts A,B,C & General as manpower shortage substitute.
- b) To clean the mezzanine floor of belt filter area or any other places as per direction of Engineer-in-charge of their representative, if any spillage/overflow of slurry during operation of HBF.

2. Removing of spillages in Lime Stone Handling Plant-

The contractor will engage persons to clean spillages generated around limestone grinding mill, spillages around ground hopper & C1 and C2 conveyors, on 2nd floor and 1st floor i.e. around crusher and screen areas respectively on daily basis and dispose them through conveyor belt and / or as advised by the Engineer-In charge.

3. Removing of spillages in Magnetite Plant-

The contractor will engage persons to clean spillages generated around magnetite grinding mills, magnetite drum area on top floor, around ground floor, etc. on daily basis and charge them to magnetite pits and / or as advised by the Engineer-In-charge.

4. Replacement of belt filter and precoat filter clothes and other related jobs:

- a) Removing of spilled slurry around belt filters area, precoat filter area
- b) Shifting of old & replaced filter clothes & nylon strings for jobs to a location within the plant as per direction of the Engineer-In-Charge.

5. Silex shifting from a distance of 200 Mtrs and charging into Ion Exchange columns.

6. Resin Shifting from a distance of 200 Mtrs and charging into Ion Exchange columns.

7. Making acidified water and decontamination of drying unit, PPN unit and peroxide area.

Handwritten signature

8. Removing the neutralizing Pachuca's and shifting the scaled material in the designated places.
9. Any other jobs related to housekeeping under the chemical "C" plant as per direction of Section in charge or Shift in-charge.
10. To work in other miscellaneous jobs as per instruction of Engineer in charge and their representative.
11. Replacement of belt filter and precoat filter clothes and other related jobs:
 - a) Removing of spilled slurry around belt filters area, precoat filter area
 - b) Shifting of old & replaced filter clothes & nylon strings for jobs to a location within the plant as per direction of the Engineer-In-Charge.
12. Silex shifting from a distance of 200 Mtrs and charging into Ion Exchange columns.
13. Resin Shifting from a distance of 200 Mtrs and charging into Ion Exchange columns.
14. Making acidified water and decontamination of drying unit, PPN unit and peroxide area.
15. Removing the neutralizing Pachuca's and shifting the scaled material in the designated places.
16. Any other jobs related to housekeeping under the chemical "C" plant as per direction of Section in charge or Shift in-charge.
17. To work in other miscellaneous jobs as per instruction of Engineer in charge and their representative.

(Handwritten signature)