

SCOPE OF WORK

1. Three numbers of Calibration and Functional checking of Draeger X-AM5600 Multigas Detector (CO₂, SO₂, NO, O₂ & CO Gas sensor). After calibration Test and Calibration certificate should be provided.
2. Three numbers of Calibration and Functional checking of Draeger X-AM5600 Multigas Detector (NO₂, H₂S&EO Gas sensor). After calibration Test and Calibration certificate should be provided.
3. Tenure of the above Job will be 1 year, two times calibration and frequency of calibration will be 06 month.

must.